




CE-H26911-S1 Update firmware


for all HDMI output ports support audio extract

1. Remove power cable
2. Please adjust mode dip switch [pin1]=[↓]
3. Connect the Micro-USB cable between PC and device
4. Plug-in power cable
5. Open the firmware update software


	CE-H26911-S1-audio-extract_Firmware_V...	1/5/2022 6:25 PM	H00 File	149 KB
	CE-H26911-S1-audio-extract_Firmware_V...	1/5/2022 6:24 PM	H01 File	144 KB
	CE-H26911-S1-audio-extract_Firmware_V...	1/5/2022 6:24 PM	H02 File	147 KB
	EPConsole_3.9.9	9/20/2017 10:33 AM	Application	195 KB

6. Set the correct COM port and baud rate (57600 is recommended)







7. Click the FILE button to load firmware file (.hex or .bin file)



8. Press Program MCU symbol to do firmware update



9. Update finished



10. If update fail, please remove Micro-USB cable and Power cable then repeat update again.
11. Once update process is done, please power cycle the device and set the dip switch [pin1] to [↑]